

Superfund Site Strategy Recommendation

Region 6

Site Name: Austin Gaslight Company Site Number: TXD 987989357

Alias Site Name(s): _____

Address: _____

City/County or Parish/State/Zip: Austin / Tarrant / TX

Recommendation:

- ☐ 1. No further remedial action planned under Superfund.
- ☐ 2. Further pre-remedial investigative action needed under Superfund:

PA _____ Priority: High _____ Medium _____
SSI _____
LSI _____
Other _____
To be performed by _____

- ☐ 3. Action may be appropriate under other authority: RCRA _____
NPDES _____ SPCC _____ 404 _____ TSCA _____ UIC _____
SMCRA _____ State _____ Other _____

Discussion:

An off-site recon inspection was performed by FIT at this site. There were no visible signs of the defunct Austin Gaslight Company's coal gasification plant. Thus, a Preliminary Assessment was not conducted.

SUPERFUND FILE

SEP 17 1992

REORGANIZED

Copies to (please list): TWC (SSSR only), GW-3, GE-E, AT30R, GH-C

Recommended By: Bill Taylor

Date: 8/31/90

Approved By: Bill Taylor

Date: 8/31/90